

39848

REMEDIAL INVESTIGATION




PLATE 1
SURFACE WATER, LEACHATE
AND SEDIMENT /SOIL SAMPLING LOCATION
COMBE SOUTH LANDFILL